

# Final Reclamation Inspection

March 30, 2021

Operator: NOBLE ENERGY INC - #100322

Location ID: 425450

Inspection Document #: 697502729

Weld County, CO

NESW Section 18 T4N R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

Inspection Photos  
Location Name: OSTER C19-27D  
Location ID: 425450



**Photo 1.** Photo taken from the well location, facing Northeast. Photo illustrates 2 of the 8 wells, confirming the 9th well has been plugged and abandoned.



Inspection Photos  
Location Name: OSTER C19-27D  
Location ID: 425450



**Photo 2.** Photo taken from the well location, facing Northeast. Photo illustrates 6 of the 8 wells, confirming the 9th well has been plugged and abandoned.

