

Final Reclamation Inspection

March 30, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 323110

Inspection Document #: 697502733

Weld County, CO

SWNE Section 18 T4N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: FRICK #32-18
Location ID: 323110



Photo 1. Photo taken from the well location, facing North. Photo illustrates Operator has performed additional final reclamation activities with the evidence of desirable establishment of vegetation. However, there is not uniform vegetative growth; therefore, it will remain in process.

Inspection Photos
Location Name: FRICK #32-18
Location ID: 323110



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: FRICK #32-18
Location ID: 323110



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: FRICK #32-18
Location ID: 323110



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: FRICK #32-18
Location ID: 323110



Photo 5. Reference photo taken west of the well location.