



- Photo 1 – Area of oil stained soil in the northeast area of the location





- Photo 2 – Area of coarse sand in the northeast corner of the location





- Photo 3 – Area of coarse sand in the northeast corner of the location, view west-southwest. Area of oil stained soil just under the truck in the photo.






- Photo 4 – Area of coarse sand in the northeast corner of the location, view south.





- Photo 5 – Area of coarse sand in the northeast corner of the location, view west-northwest.





- Photo 6 – Standing water, crusted soil, view northwest





- Photo 7 – Standing water further south from previous photo, crusted soil, view northwest



- Photo 8 – Standing water further south from previous photo, crusted soil, view north





- Photo 9 – View north from southern end of the location





- Photo 10 – View northeast from playa southeast of the location (top of truck and windmill visible top center)





- Photo 11 – Junk pipe in northwest area of the location





- Photo 12 – Oil stained soil close-up. View west from northwest area of the location





- Photo 13 – Junk pipe, crusted soil in northern area of the location





- Photo 14 – View south across crusted soil and standing water from the northern area of the location





- Photo 15 – View north from the northeastern area of the location





- Photo 16 – View southeast from the northeastern area of the location





- Photo 17 – View south along western edge of the location from the northeastern area of the location





- Photo 18 – Concrete slabs on the western edge and adjacent to the northeastern area of the location





- Photo 19 – Oil stained soil in the northwestern area of the location, view east





- Photo 20 – Junk pipe bordering the northwestern area of the location, view east





- Photo 21 – Junk pipe bordering the northwestern area of the location, view east





- Photo 22 – oil stained soil in the northwestern area of the location, view east





- Photo 23 – oil stained soil in the northwestern area of the location





- Photo 24 – oil stained soil in the northwestern area of the location





- Photo 25 – oil stained soil in the northwestern area of the location