

**Caerus Piceance LLC**  
**N32**  
**Location # 334856**

Mar 24, 2021 at 11:10:49 AM  
COGCC



**Previous inspection**

Mar 30, 2021 at 10:36:48 AM  
39.523780,-107.764725 ±48.29m  
COGCC



**Follow up inspection**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Caerus Piceance LLC  
N32  
Location # 334856



Follow up inspection



Follow up inspection



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Caerus Piceance LLC**  
**N32**  
**Location # 334856**

Mar 30, 2021 at 11:11:55 AM  
39.476872,-107.693997 ±33.14m  
COGCC



Mar 30, 2021 at 11:13:51 AM  
39.477556,-107.693683 ±35.04m  
COGCC



**Follow up inspection**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Caerus Piceance LLC  
N32  
Location # 334856



**Previous inspection**



**Follow up inspection**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Caerus Piceance LLC  
N32  
Location # 334856

Mar 24, 2021 at 11:34:19 AM  
39.477830,-107.693593 ±4.78m  
COGCC



**Previous inspection**

Mar 30, 2021 at 11:14:56 AM  
39.477886,-107.693638 ±4.77m  
COGCC



**Follow up inspection**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Caerus Piceance LLC  
N32  
Location # 334856

Mar 24, 2021 at 11:36:05 AM  
39.478135,-107.694083 ±4.79m  
COGCC



**Previous inspection**

Mar 30, 2021 at 11:16:29 AM  
39.478173,-107.694304 ±4.78m  
COGCC



**Follow up inspection**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Caerus Piceance LLC**  
**N32**  
**Location # 334856**

Mar 30, 2021 at 11:20:41 AM  
39.477774,-107.693778 ±6.29m  
COGCC



**Follow up inspection One new dead man found with grader**

Mar 30, 2021 at 11:18:25 AM  
39.477994,-107.694192 ±4.75m  
COGCC



**Chemical containment with fluid level high**