

TEP ROCKY MOUNTAIN LLC CHEVRON-66S96W 17NWSE Location # 335587



Battery sign replaced and installed at tank battery.

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 17NWSE
Location # 335587**



Culvert in process of being cleaned out.



Ditch groomed.

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 17NWSE
Location # 335587**



Culvert in process of being cleaned out.



Tubing being used to clean out clean out culvert, unsure if it is the unused tubing form previous inspection.

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 17NWSE
Location # 335587**



Crew working to clean out culvert.