

Inspection Photos
Location Name: McCallum 173
Location ID: 324734



Photo 1. Overview of location taken facing west.




Photo 2. No bradenhead access apparent.

