

**Inspection Photos**  
**Location Name: McCallum Unit 116**  
**Location ID: 324690**



**Photo 1. Overview of location taken facing south.**



**Photo 2. No bradenhead access apparent.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources