

# CAERUS PICEANCE LLC CHEVRON-66S96W 17SENW Location # 335581



Sticker peeling off battery sign.

**CAERUS PICEANCE LLC**  
**CHEVRON-66S96W 17SEW**  
**Location # 335581**



**CAERUS PICEANCE LLC  
CHEVRON-66S96W 17SEW  
Location # 335581**



**Perimeter ditch needs cleaned out.**



**Perimeter ditch needs cleaned out.**

**CAERUS PICEANCE LLC  
CHEVRON-66S96W 17SEW  
Location # 335581**



**Check dam above location behind tank battery  
needs cleaned out.**

**CAERUS PICEANCE LLC  
CHEVRON-66S96W 17SEW  
Location # 335581**



**Erosion from the storm water flow coming from check dam.**

**CAERUS PICEANCE LLC**  
**CHEVRON-66S96W 17SEnw**  
**Location # 335581**



**Ditch needs cleaned out.**