

Inspection Photos

3/31/2021

Operator: SG INTERESTS I LTD # 77330

Location ID: 429333

Gunnison County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: SG INTERESTS I LTD # 77330

Location ID: 429333



Photo 1: Photo taken from the southern entrance. Photo shows signage has been installed per form 4 and Delayed IR NTO COAs.

Inspection Photos
Operator Name: SG INTERESTS I LTD # 77330
Location ID: 429333



Photo 2: Photo taken from the top of the berm along the northern perimeter of the Pad. Photo shows example of crack/stabilization issues observed throughout the perimeter of the Location and slopes.

Inspection Photos
Operator Name: SG INTERESTS I LTD # 77330
Location ID: 429333



Photo 3: Photo taken from the slopes on the southeast end of the Location. Photo shows example of crack/stabilization issues observed throughout the perimeter of the Location and slopes. 6 foot measuring stick for reference.

Inspection Photos

Operator Name: SG INTERESTS I LTD # 77330

Location ID: 429333



Photo 4: Photo taken from crack on the perimeter of the Location. Photo shows example of areas where cracks on the Location were observed to exceed 30 inches in depth.

Inspection Photos

Operator Name: SG INTERESTS I LTD # 77330

Location ID: 429333



Photo 5: Photo taken from the south end of the Location. Photo shows Sediment trap has not been constructed in accordance with good engineering practices; BMP not constructed with an appropriate inlet/outlet.

Inspection Photos

Operator Name: SG INTERESTS I LTD # 77330

Location ID: 429333



Photo 6: See comments under photo 5.

Inspection Photos

Operator Name: SG INTERESTS I LTD # 77330

Location ID: 429333



Photo 7: Photo taken from the southern areas of the Location. Photo shows Musk thistle remnants from the 2020 growing season. Common mullein also observed on Location. These are Colorado State listed noxious weeds.