

**Inspection Photos
Cosslet A 9 Flowline
Spill ID 478542 (AC)**



Photo 1 – Free product observed on groundwater in open excavation. Weeds/debris in open excavation



Photo 2 – Free product observed on groundwater in open excavation.

**Inspection Photos
Cosslet A 9 Flowline
Spill ID 478542 (AC)**



Photo 3 – Soils stored on site.



Photo 4 – Soils stored on site with no BMPs

Inspection Photos
Cosslet A 9 Flowline
Spill ID 478542 (AC)



Photo 5 – Fencing is down around open excavation.



Photo 6 – Fencing is down around open excavation.