

# Inspection Photos

API: 071-07943

Operator: OGRIS OPERATING LLC

Inspection Date: 4/1/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-07943 | Date: 4/1/2021

## Inspection Photos



**Photo 1.** There are areas along the main road which are rutted and not maintained.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07943 | Date: 4/1/2021



## Inspection Photos



**Photo 2.** Facing toward the access road. The access road is rutted and not stabilized and maintained.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07943 | Date: 4/1/2021



## Inspection Photos



**Photo 3.** Facing back down toward the access road. Hard hat was placed in vehicle rut for scale.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07943 | Date: 4/1/2021



## Inspection Photos



**Photo 4.** Facing toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07943 | Date: 4/1/2021

## Inspection Photos



**Photo 5.** There is oil stained soil and oil in the engine skid which needs to be cleaned up.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07943 | Date: 4/1/2021