

Inspection Photos
Location Name: RSU-Anchutz Federal 4-62-11_12 SE10
Location ID: 454976



Photo 1 – Tank Battery Sign

Photo 2 – Tank Battery

Inspection Photos
Location Name: RSU-Anchutz Federal 4-62-11_12 SE10
Location ID: 454976



Photo 3 – Separators



Photo 4 – ECDs

Inspection Photos
Location Name: RSU-Anchutz Federal 4-62-11_12 SE10
Location ID: 454976



Photo 5 – VRUs

Photo 6 – Wellheads

Inspection Photos
Location Name: RSU-Anchutz Federal 4-62-11_12 SE10
Location ID: 454976




Photo 7 – Missing Capacity Label

Photo 8 – Label is starting to fade – Replace soon

Inspection Photos
Location Name: RSU-Anchutz Federal 4-62-11_12 SE10
Location ID: 454976



Photo 9 – Label is starting to fade

Photo 10 – Label is starting to fade

Inspection Photos

Location Name: RSU-Anchutz Federal 4-62-11_12 SE10

Location ID: 454976



Photo 11 – Riser has been marked

Photo 12 – Riser has been marked