

Location ID: 454977



Photo 2 – Tank Battery

Inspection Photos

Location Name: RSU-Anchutz Federal 4-62-2_1 SE3

Location ID: 454977



Photo 3 – Separators



Photo 4 – ECDs



Inspection Photos
Location Name: RSU-Anchutz Federal 4-62-2_1 SE3
Location ID: 454977



Photo 5 – Wellheads



Photo 6 – Risers have been marked

Inspection Photos

Location Name: RSU-Anchutz Federal 4-62-11_12 SE10

Location ID: 454976



Photo 7 – Risers have been marked



Photo 8 – Risers have been marked