

Inspection Photos
Location Name: 70 Ranch State BB18-655 Multi
Location ID: 441841



Photo #1 Wells

Photo #2 Location

Inspection Photos
Location Name: 70 Ranch State BB18-655 Multi
Location ID: 441841




Photo #3 Mechanical Conditions

Photo #4 Oily Waste

Inspection Photos
Location Name: 70 Ranch State BB18-655 Multi
Location ID: 441841



Photo #5 Inadequate Berms

Photo #6 Inadequate Berms

Inspection Photos
Location Name: 70 Ranch State BB18-655 Multi
Location ID: 441841




Photo #7 Unused Equipment



Photo #8 Unused Equipment

Inspection Photos
Location Name: 70 Ranch State BB18-655 Multi
Location ID: 441841



Photo #9 Unused Equipment