

**TEP ROCKY MOUNTAIN LLC  
GV-66S95W 32NESW  
Location # 323835**



**Well sign is in poor condition. Cracking and peeling.**

**TEP ROCKY MOUNTAIN LLC**  
**GV-66S95W 32NESW**  
**Location # 323835**



Well sign is in poor condition. Cracking and peeling.



Well sign is in poor condition. Cracking and peeling.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources