

Inspection Photos
Location Name: Craig #2
Location ID: 327437



Photo 1 – Pumping Unit

Photo 2 – Wellhead Sign

Inspection Photos
Location Name: Craig #2
Location ID: 327437



Photo 3 – Wellhead



Photo 4 – Heater Treater

Inspection Photos
Location Name: Craig #2
Location ID: 327437



Photo 5 – Tank Battery



Photo 6 – Gas Meter Calibration Card is up to date

Inspection Photos
Location Name: Craig #2
Location ID: 327437



Photo 7 – Stained Soil at Gas Engine



Photo 8 – Stained Soil at Gas Engine

Inspection Photos
Location Name: Craig #2
Location ID: 327437



Photo 9 – Stained Soil at Gas Engine

Photo 10 – Stained Soil and Unmarked Deadman

Inspection Photos
Location Name: Craig #2
Location ID: 327437



Photo 11 – Unused Pipe in NE Corner



Photo 12 – Pit

Inspection Photos
Location Name: Craig #2
Location ID: 327437



Photo 13 – Pit



Photo 14 – Pit

Inspection Photos
Location Name: Craig #2
Location ID: 327437



Photo 15 – Pit