

Inspection Photos
Location Name: Bighole-Fed Land Bank 13-1
Location ID: 312931



Photo 1. Overview of location taken at the wellhead facing northwest. Wellhead sign knocked over and inaccurate.



Photo 2. Overview of location taken at the wellhead facing southeast.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Bighole-Fed Land Bank 13-1
Location ID: 312931



Photo 3. Rills on location.



Photo 4. Rills leaving location. Chemical totes without secondary containment on location perimeter.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Bighole-Fed Land Bank 13-1
Location ID: 312931



Photo 5. Rills leaving location.



Photo 6. Tank battery with missing and incomplete tank labels.



Inspection Photos
Location Name: Bighole-Fed Land Bank 13-1
Location ID: 312931



Photo 7. Active leak, ongoing release from flowline.



Photo 8. Spilled fluid in tank battery. Photo taken adjacent to berm breach.



Inspection Photos
Location Name: Bighole-Fed Land Bank 13-1
Location ID: 312931



Photo 9. Berm breach. Spill leaving location.



Photo 10. Berm breach. Spill leaving location.



Inspection Photos
Location Name: Bighole-Fed Land Bank 13-1
Location ID: 312931



Photo 11. Spill leaving location.



Photo 12. Spill leaving location.



Inspection Photos
Location Name: Bighole-Fed Land Bank 13-1
Location ID: 312931



Photo 13. Photo of spill pathway looking towards location.



Photo 14. Photo of spill pathway looking towards location.



Inspection Photos
Location Name: Bighole-Fed Land Bank 13-1
Location ID: 312931



Photo 15. Stained soil in berm.



Photo 16. Stained soil in berm.



Inspection Photos
Location Name: Bighole-Fed Land Bank 13-1
Location ID: 312931



Photo 17. Stained soil in berm.



Photo 18. Stained soil in berm. Animal footprints (pronghorn and deer) visible around perimeter of fluid puddle.



Inspection Photos
Location Name: Bighole-Fed Land Bank 13-1
Location ID: 312931



Photo 19. Stained soil in berm.



Photo 20. Stained soil in berm and fluid in berm.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources