

Inspection Photos  
Location Name: Tabor #7  
Location ID: 321338



Photo 1 WH sign



Photo 2 WH

**Inspection Photos**  
**Location Name: Tabor #7**  
**Location ID: 321338**



**Photo 3 Stained soil by the WH**



**Photo 4 Separator and Crude tank**

**Inspection Photos**  
**Location Name: Tabor #7**  
**Location ID: 321338**



**Photo 5 Graffiti on Horizontal Heated Separator**




**Photo 6 Graffiti on Horizontal Heated Separator**



**Location ID: 321338**



### Photo 7 Gas Meter Run



**Photo 8 Card in meter house indicates current calibration**

Inspection Photos  
Location Name: Tabor #7  
Location ID: 321338



Photo 9 TB sign



Photo 10 Graffiti on crude tank