


CM Production Bond Claim: Task 3.1 - Mechanical Integrity Test - 324634, 057-06031
Margaret Spaulding #4

Prepared 3/2/2021

FIELD NAME Lone Pine
FIELD NUMBER 51375

LOCATION
Basin North Park
Location-Section-Township-Ran SWSE 28 9N 81W
Location-Lat/Long 40.718608/-106.498828
Elevation 8,221' KB
8,214' GR



COGCC Document No.

Status SI 1/1/2012

Notes:
Spud 6/12/1972
Last MIT 9/30/2013
Pump jack Yes
Rods and pump ?
Tubing size ?
Tubing depth ?
Need to pull rods & pump

