


CM Production Bond Claim: Task 3.1 - Mechanical Integrity Test - 324627, 057-06070  
Margaret Spaulding 8

Prepared	3/2/2021		
FIELD NAME	Lone Pine		
FIELD NUMBER	51375		
<u>LOCATION</u>			
Basin	North Park		
Location-Section-Township-Range	NWSE 28 9N81W		
Location-Lat/Long	40.722103/-106.496571		
Elevation	8,177	KB	
	8,164	GR	



COGCC Document No.	
Status	SI 8/1/2014
<u>Notes:</u>	
Spud	5/23/1973
Last MIT	NA
Pump jack	Yes
Rods and pump	?
Tubing size	79 jts 2-7/8" 6.5 ppf ?
Tubing depth	2440'?
Need to pull rods & pump	

