


CM Production Bond Claim: Task 3.1 - Mechanical Integrity Test - 324628, 057-06080
Margaret Spaulding 9

| | | | |
|---------------------------------|----------------------|----|--|
| Prepared | 3/2/2021 | | |
| FIELD NAME | Lone Pine | | |
| FIELD NUMBER | 51375 | | |
| <u>LOCATION</u> | | | |
| Basin | North Park | | |
| Location-Section-Township-Range | SENE 33 9N81W 6 PM | | |
| Location-Lat/Long | 40.71211/-106.492479 | | |
| Elevation | 8,615 | KB | |
| | 8,608 | GR | |



| | |
|--------------------|--------------------|
| COGCC Document No. | |
| Status | SI 8/1/2014 |
| <u>Notes:</u> | |
| Spud | 8/21/1973 |
| Last MIT | NA |
| Pump jack | Reda Pump w/ cable |
| Rods and pump | ? |
| Tubing size | ? |
| Tubing depth | ? |

