

**CM Production Bond Claim: Task 3.1 - Mechanical Integrity Test - 324630, 057-06093
Margaret Spaulding 11**

Prepared 3/2/2021

FIELD NAME Lone Pine
FIELD NUMBER 51375

LOCATION
Basin North Park
Location-Section-Township-Range SWSE 28 9N81W
Location-Lat/Long 40.719956/-106.500367
Elevation 8,205 KB
8,198 GR

COGCC Document No.

Status SI 3/25/2013
Notes:
Spud 1/14/1974
Last MIT NA
Pump jack Yes
Rods and pump Laid down
Tubing size ?
Tubing depth ?

