


CM Production Bond Claim: Task 3.1 - Mechanical Integrity Test - 324633, 057-06100  
Margaret Spaulding 13

Prepared	3/2/2021		
FIELD NAME	Lone Pine		
FIELD NUMBER	51375		
<u>LOCATION</u>			
Basin	North Park		
Location-Section-Township-Ra	SESE 28 9N81W 6 PM		
Location-Lat/Long	40.719905/-106.495677		
Elevation	8,254	KB	
	8,247	GR	



COGCC Document No.	
Status	SI 7/17/2015
<u>Notes:</u>	
Spud	5/31/1974
Last MIT	8/19/2013
Pump jack	Yes
Rods and pump	96-1/4" (66) rods + 2-1" weight rods on bottom, 2"x1-1/2" RWBCx16'x20' 163" stroke pump
Tubing size	2-3/8" J55 4.7ppf at w/anchor at 2,444' KB set in 15K tension
Tubing depth	2,552'
Need to pull rods & pump	

Deepest water well within 2 miles is 217'

