


CM Production Bond Claim: Task 3.1 - Mechanical Integrity Test - 324635, 057-06112
Margaret Spaulding 15

Prepared 3/2/2021

FIELD NAME Lone Pine
FIELD NUMBER 51375

LOCATION
Basin North Park
Location-Section-Township-Range SESE 28 9N81W 6 PM
Location-Lat/Long 40.717395/-106.494593
Elevation 8,268 KB
8,260 GR



COGCC Document No.

Status: SI 3/25/2013
Notes:
Spud 7/21/1974
Last MIT NA
Pump jack Yes
Rods and pump Unscrewed below polish
Tubing size 2-3/8"?
Tubing depth 2533' ?
Need to pull rods & pump

