


**CM Production Bond Claim: Task 3.1 - Mechanical Integrity Test - 324637, 057-06115
Margaret Spaulding 16**

Prepared 3/2/2021

FIELD NAME Lone Pine
FIELD NUMBER 51375

LOCATION

Basin North Park
Location-Section-Township-Range NWSE 28 9N81W
Location-Lat/Long 40.723674/-106.497717
Elevation 8,192 KB
8,185 GR



COGCC Document No.

Status SI 3/25/2013
Notes:
Spud 10/4/1974
Last MIT NA
Pump jack Hydraulic jet pump
Rods and pump ?
Tubing size 2-3/8" ?
Tubing depth 2492 ?
Need to pull rods and pump

