


CM Production Bond Claim: Task 3.1 - Mechanical Integrity Test - 324640, 057-06127  
Margaret Spaulding 18

Prepared 3/2/2021

FIELD NAME Lone Pine  
FIELD NUMBER 51375

LOCATION  
Basin North Park  
Location-Section-Township-Rang NWSE 28 9N81W  
Location-Lat/Long 40.723245/-106.50107  
Elevation 8,243 KB  
8,233 GR



COGCC Document No.

Status SI 8/1/2014  
Notes:  
Spud 1/11/1976  
Last MIT NA  
Pump jack Yes  
Rods and pump ?  
Tubing size 2-3/8" ?  
Tubing depth 2212' ?  
Need to pull rods and pump

