



40.13305, -108.20588, 6056.7ft, 150°
04/06/2021 04:33:37 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Well.

WRD Federal 19-13

API: 05-103-09921

Inspection: 701500230



40.13296, -108.20588, 6065.7ft, 59°
04/06/2021 04:33:49 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Separator.

WRD Federal 19-13

API: 05-103-09921

Inspection: 701500230





COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Tanks.

WRD Federal 19-13

API: 05-103-09921

Inspection: 701500230



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 7. Gap in tank secondary containment.

WRD Federal 19-13

API: 05-103-09921

Inspection: 701500230



40.1324, -108.20605, 6053.7ft, 108°
04/06/2021 04:37:16 PM