

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS-67S96W /35NWNW

Location ID: 334114



Photo #3392 from entrance to location.



Photo #3393 from entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS-67S96W /35NWNW

Location ID: 334114



Photo #3394 Location lacks stabilization.



Photo #3395 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS-67S96W /35NWNW

Location ID: 334114



Photo #3396 No form of tracking control at entrance to location.