

Wilmoth 14-06

05-123-17738

During the Form 17, completed on 10/7/2020, a bradenhead and production gas sample was collected, and those results have been submitted via a Form 43 on 12/17/2020. A Form 4 for bradenhead mitigation was approved on 10/28/2020. The first blow down was on 11/30/2020, with a starting pressure of 32 psi, and collected 7 Mcf of gas for an approximate flow rate of 0.35 Mcf/minute and collected 0 gallons of fluid from the bradenhead but did not flow. The second blow down, on 2/1/2021, had a starting pressure of 24 psi, and collected 3.7 Mcf of gas for an approximate flow rate of 0.12 Mcf/minute, and collected 0 gallons of fluid from the bradenhead but did not flow. The third blow down, on 3/29/2021, had a starting pressure of 26 psi, and collected 3.9 Mcf of gas for an approximate flow rate of 0.27 Mcf/minute, and collected 0 gallons of fluid from the bradenhead but did not flow. On 4/5/2021, a Form 17 was completed with a starting pressure of 14 psi and an ending pressure of 0 psi. This well is in compliance with Order 1-232 and will be returned to annual testing.

