

Inspection Photos

4/6/2021

Operator: LARAMIE ENERGY LLC

Location ID: 334502

Mesa County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC
Location ID: 334502



Photo 1: Photo shows sign at Location entrance

Inspection Photos
Operator Name: LARAMIE ENERGY LLC
Location ID: 334502



Photo 2: Photo taken from the west end of the Location, facing northeast. Photos 1-2 provide an overview of the Location from northwest to southeast. Photo also shows gravel on production areas is beginning to fill with sediment. Maintenance advised to ensure control measure remains in proper functioning condition to stabilize Location and prevent offsite sediment transport.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC
Location ID: 334502



Photo 3: See comments under photo 2.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC
Location ID: 334502



Photo 4: Photo taken from the interim areas on the south end of the Location. Areas appear to be progressing towards 1003 standards.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC
Location ID: 334502



Photo 5: Photo shows example of cheatgrass establishment observed throughout interim areas.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC
Location ID: 334502



Photo 6: Photo taken from the northeastern interim areas of the Location. Interim areas on the northern/eastern end of the Location may required additional seeding to facilitate reclamation towards 1003 standards.