

Inspection Photos

4/6/2021

Operator: LARAMIE ENERGY LLC #10433

Location ID: 334542

Mesa County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 334542



Photo 1: Photo taken from the west end of the Location, facing north. Interim areas appear to be progressing towards 1003 standards.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 334542



Photo 2: Photo shows control measures to manage stormwater runoff.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 334542



Photo 3: Photo shows control measures to manage stormwater runoff.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 334542



Photo 4: Photo shows producing wells on the Location. Photo also shows gravel has filled with sediment; advise maintenance to ensure pad remains stabilized and to prevent offsite sediment transport.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 334542



Photo 5: Photo taken from the north east end of the Location, facing south. Photo shows interim areas appear to be progressing towards 1003 standards.