

Marble 34-33



Cleaned up Engine skid to comply with Rule 1002.f.(2)A and comply with general provisions of the oil and gas act for wildlife protection

Cleaned up





Conducted maintenance on equipment, cleaned up stained material and reviewed self-inspection process to comply with Rule 1002..(2).D.