

Inspection Photos

4/6/2021

Operator: LARAMIE ENERGY LLC #10433

Location ID: 312443

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 312443



Photo 1: Photo of sign at Location entrance.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 312443



Photo 2: Photo taken from the east end of the Location, facing southwest. Photos 2-3 provide an overview of the Location from southwest to west; photos show reclamation is not progressing towards COGCC 1004 standards; Location appears to be in use as a storage area; not 502.b variance has been approved to waive reclamation requirements.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 312443



20210406

Photo 3: See comments under photo 2.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 312443



Photo 4: Photo taken from the west end of the Location, facing east. Photos 4-6 provide an overview of the Location from east, southeast to south; photos show reclamation is not progressing towards COGCC 1004 standards; Location appears to be is use as a storage area; not 502.b variance has been approved to waive reclamation requirements.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 312443



Photo 5: See comments under photo 4.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 312443



Photo 6: See comments under photo 4