

SWMP INSPECTION REPORTING FORM

Well Name: Weigel 29-01 Line Leak 11-3-20 Legal Description: NENE/4 SEC 29-T01N-R44W

Reason for Routine Inspection: ___ 14-Day Interval X 30-Day Interval. ___ Significant Storm Event.

Spill Point ID: 478494

Weather information since last inspection was held.

Event	Date Began	Amount (Inches)	Event	Date Began	Amount (Inches)
1			2		
3			4		

Best Management Practices	Overall Condition	Need Repair	G=Good, F=Fair, P=Poor, N/A=Not Applicable Comments
Perimeter BMPs			
Straw Bales/Rolls	G F P <u>N/A</u>	Y <u>N</u>	
Silt Fence	G F P <u>N/A</u>	Y <u>N</u>	
Berms/Dikes/Ditches	G F P <u>N/A</u>	Y <u>N</u>	
Slope BMPs			
Surface Roughening	G F P <u>N/A</u>	Y <u>N</u>	WAITING FOR SPRING SPROUT / Need Gypsum out of stock
Straw mulch	G F P <u>N/A</u>	Y <u>N</u>	
Perennial Vegetation	G F P <u>N/A</u>	Y <u>N</u>	

Will existing BMPs need to be modified or removed or additional BMPs Installed? YES NO
If yes, list the action items to be completed on the table below.

Are uncontrolled releases of mud or sediment from the site evident? YES NO
If yes, what corrective actions are to occur – describe on table below.

Are non-compliance incidents evident? YES NO If no, sign the certification at the bottom of this form: If yes, describe actions to be completed below.

Actions to be Completed	Date Completed
1	
2	
3	

I certify the site is in compliance with the SWMP and this permit: E. Republican/OM

Old Permit: COR 03H496 / New Permit: COR 403419

Inspection completed on 03/22/2021

by: 

Title of inspector: Lease Attendant

4-6-21

SWMP INSPECTION REPORTING FORM

Well Name: Weigel 29-01 Line Leak 11-3-20 Legal Description: NENE/4 SEC 29-T01N-R44W

Reason for Routine Inspection: ___ 14-Day Interval X 30-Day Interval. ___ Significant Storm Event.

Spill Point ID: 478494

Weather information since last inspection was held.

Event	Date Began	Amount (Inches)		Event	Date Began	Amount (Inches)
1				2		
3				4		

Best Management Practices	Overall Condition	Need Repair	<u>G=Good, F=Fair, P=Poor, N/A=Not Applicable</u> Comments
Perimeter BMPs			
Straw Bales/Rolls	G F P <u>(N/A)</u>	Y <u>(N)</u>	
Silt Fence	G F P <u>(N/A)</u>	Y <u>(N)</u>	
Berms/Dikes/Ditches	G F P <u>(N/A)</u>	Y <u>(N)</u>	
Slope BMPs			
Surface Roughening	G F P <u>(N/A)</u>	Y <u>(N)</u>	Need Gypsum Sprinkled
Straw mulch	G F P <u>(N/A)</u>	Y <u>(N)</u>	
Perennial Vegetation	G F <u>(P)</u> <u>(N/A)</u>	Y <u>(N)</u>	

Will existing BMPs need to be modified or removed or additional BMPs Installed? YES (NO)
If yes, list the action items to be completed on the table below.

Are uncontrolled releases of mud or sediment from the site evident? YES (NO)
If yes, what corrective actions are to occur – describe on table below.

Are non-compliance incidents evident? YES (NO) If no, sign the certification at the bottom of this form: If yes, describe actions to be completed below.

Actions to be Completed	Date Completed
1	
2	
3	

I certify the site is in compliance with the SWMP and this permit: E. Republican/OM

Old Permit: COR 03H496 / New Permit: COR 403419

Inspection completed on 02/26/2021

by: _____

Omar Mah...

Title of inspector: Lease Attendant

MM 4-6-21

SWMP INSPECTION REPORTING FORM

Well Name: Weigel 29-01 Line Leak 11-3-20 Legal Description: NENE/4 SEC 29-T01N-R44W

Reason for Routine Inspection: ___ 14-Day Interval, X 30-Day Interval, ___ Significant Storm Event.

Spill Point ID: 478494

Weather information since last inspection was held.

Event	Date Began	Amount (Inches)	Event	Date Began	Amount (Inches)
1			2		
3			4		

Best Management Practices	Overall Condition	Need Repair	G=Good, F=Fair, P=Poor, N/A=Not Applicable Comments
Perimeter BMPs			
Straw Bales/Rolls	G F P <u>N/A</u>	Y <u>N</u>	
Silt Fence	G F P <u>N/A</u>	Y <u>N</u>	
Berms/Dikes/Ditches	G F P <u>N/A</u>	Y <u>N</u>	
Slope BMPs			
Surface Roughening	G F P <u>N/A</u>	Y <u>N</u>	<i>Needs Gypsum Sprinkled</i>
Straw mulch	G F P <u>N/A</u>	Y <u>N</u>	
Perennial Vegetation	G F P <u>N/A</u>	Y <u>N</u>	

Will existing BMPs need to be modified or removed or additional BMPs Installed? YES NO
If yes, list the action items to be completed on the table below.

Are uncontrolled releases of mud or sediment from the site evident? YES NO
If yes, what corrective actions are to occur – describe on table below.

Are non-compliance incidents evident? YES NO If no, sign the certification at the bottom of this form: If yes, describe actions to be completed below.

Actions to be Completed	Date Completed
1	
2	
3	

I certify the site is in compliance with the SWMP and this permit: E. Republican/OM

Old Permit: COR 03H496/ New Permit: COR 403419

Inspection completed on 01/29/2021 by: *[Signature]*

Title of inspector: Lease Attendant

[Signature]
4-6-21

12 @ Auto
glass
now

SWMP INSPECTION REPORTING FORM

Well Name: Weigel 29-01 Line Leak 11-3-20 Legal Description: NENE/4 SEC 29-T01N-R44W

Reason for Routine Inspection: ___ 14-Day Interval, X 30-Day Interval. ___ Significant Storm Event.

Spill Point ID: 478494

Weather information since last inspection was held.

Event	Date Began	Amount (Inches)	Event	Date Began	Amount (Inches)
1			2		
3			4		

Best Management Practices	Overall Condition	Need Repair	G=Good, F=Fair, P=Poor, N/A=Not Applicable Comments
Perimeter BMPs			
Straw Bales/Rolls	G F P N/A	Y N	
Silt Fence	G F P N/A	Y N	
Berms/Dikes/Ditches	G F P N/A	Y N	
Slope BMPs			
Surface Roughening	<u>G</u> F P N/A	Y N	Still needs time Pasture showing Improvement
Straw mulch	G F P N/A	Y N	
Perennial Vegetation	G F P N/A	Y N	

Will existing BMPs need to be modified or removed or additional BMPs Installed? YES NO
If yes, list the action items to be completed on the table below.

Are uncontrolled releases of mud or sediment from the site evident? YES NO
If yes, what corrective actions are to occur – describe on table below.

Are non-compliance incidents evident? YES NO If no, sign the certification at the bottom of this form: If yes, describe actions to be completed below.

Actions to be Completed	Date Completed
1	
2	
3	

I certify the site is in compliance with the SWMP and this permit: E. Republican/OM

Old Permit: COR 03H496/ New Permit: COR 403419

Inspection completed on 12/30/2020

by: *[Signature]*

Title of inspector: Lease Attendant

[Handwritten Signature]

SWMP INSPECTION REPORTING FORM

Well Name: Weigel 29-01 Line Leak 11-3-20 Legal Description: NENE/4 SEC 29-T01N-R44W

Reason for Routine Inspection: 14-Day Interval, 30-Day Interval, Significant Storm Event.

Weather information since last inspection was held.

Event	Date Began	Amount (Inches)		Event	Date Began	Amount (Inches)
1				2		
3				4		

Best Management Practices	Overall Condition	Need Repair	G=Good, F=Fair, P=Poor, N/A=Not Applicable Comments
Perimeter BMPs			
Straw Bales/Rolls	G F P N/A	Y N	
Silt Fence	G F P N/A	Y N	
Berms/Dikes/Ditches	G F P N/A	Y N	
Slope BMPs			
Surface Roughening	<u>G</u> F P N/A	Y N	Dust pile needs time showing improvement
Straw mulch	G F P N/A	Y N	
Perennial Vegetation	G F P N/A	Y N	

Will existing BMPs need to be modified or removed or additional BMPs Installed? YES **NO**

If yes, list the action items to be completed on the table below.

Are uncontrolled releases of mud or sediment from the site evident? YES **NO**

If yes, what corrective actions are to occur – describe on table below.

Are non-compliance incidents evident? YES **NO** If no, sign the certification at the bottom of this form: If yes, describe actions to be completed below.

Actions to be Completed	Date Completed
1	
2	
3	

I certify the site is in compliance with the SWMP and this permit: E. Republican/OM COR 03H496

Inspection completed on 11/29/2020 by: Ann Moberg

Title of inspector: Lease Attendant

MS 1-14-21

