

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FNB OF GRAND JUNCTION TR-66S95W /36NWSE

Location ID: 334815



Photo #3423 from entrance to location.



Photo #3424 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FNB OF GRAND JUNCTION TR-66S95W /36NWSE

Location ID: 334815



Photo #3425 Location lacks stabilization.



Photo #3426 No form of tracking control at entrance to location.