

Inspection Photos
Location Name: Hooze-Bjolin 1
Location ID: 318942



Photo 1 – Tank Battery



Photo 2 – Tank Battery Sign – Contact Number has faded no longer visible



Inspection Photos
Location Name: Hooze-Bjolin 1
Location ID: 318942



Photo 3 – Pumping Unit



Photo 4 – Pumping Unit Sign

Inspection Photos
Location Name: Hooze-Bjolin 1
Location ID: 318942



Photo 5 – Stained Soil at Gas Engine Exhaust



Photo 6 – Heater Treater



Inspection Photos
Location Name: Hooze-Bjolin 1
Location ID: 318942



Photo 7 – Pit Area



Photo 8 – Produced Water Tank