

Inspection Photos

API: 071-09266

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/9/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09266 | Date: 4/9/2021

Inspection Photos



Photo 1. The sediment trap has been maintained along the access road



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09266 | Date: 4/9/2021

Inspection Photos



Photo 2. A portion of the fill slope of the location was seeded and hydromulched.



Inspection Photos



Photo 3. Well sign is posted at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09266 | Date: 4/9/2021