

Inspection Photos
Location Name: Park T-4 Pad
Location ID: 428521




Photo #1 Location

Photo #2 Unmarked Riser

Inspection Photos
Location Name: Park T-4 Pad
Location ID: 428521



Photo #3 Unmarked Riser

Photo #4 Unmarked Riser

Inspection Photos
Location Name: Park T-4 Pad
Location ID: 428521



Photo #5 Unmarked Riser



Photo #6 Unmarked Riser

Inspection Photos
Location Name: Park T-4 Pad
Location ID: 428521




Photo #7 Unmarked Riser

Photo #8 Unmarked Riser

Inspection Photos
Location Name: Park T-4 Pad
Location ID: 428521



Photo #9 Unmarked Risers

Photo #10 Unmarked Risers

Inspection Photos
Location Name: Park T-4 Pad
Location ID: 428521



Photo #11 Unmarked Riser

Photo #12 Trash

Inspection Photos
Location Name: Park T-4 Pad
Location ID: 428521



Photo #13 Stained Soil



Photo #14 Unused Equipment

Inspection Photos
Location Name: Park T-4 Pad
Location ID: 428521



Photo #15 Stained soil & Oily Waste



Photo #16 Missing wildlife protective netting

Inspection Photos
Location Name: Park T-4 Pad
Location ID: 428521



Photo #17 Trash



Photo #18 Unmarked Risers

Inspection Photos
Location Name: Park T-4 Pad
Location ID: 428521




Photo #19 Unmarked Risers

Photo #20 Unmarked Risers

Inspection Photos
Location Name: Park T-4 Pad
Location ID: 428521




Photo #21 Unmarked Riser

Photo #22 Unmarked Risers

Inspection Photos
Location Name: Park T-4 Pad
Location ID: 428521



Photo #23 Unused Jersey Barrier


Photo #24 Unmarked Risers

Inspection Photos
Location Name: Park T-4 Pad
Location ID: 428521



Apr 12, 2021 at 10:15:41 AM
+40.3343, -104.4386
Weld

Colorado Oil & Gas Conservation Commission



Apr 12, 2021 at 9:54:01 AM
+40.3345, -104.4390
Weld

Colorado Oil & Gas Conservation Commission

Photo #25 Mechanical Conditions "Valve"

Photo #26 Unmarked Risers

Inspection Photos
Location Name: Park T-4 Pad
Location ID: 428521



Photo #27 Unmarked Riser



Photo #28 Unmarked Risers

Inspection Photos
Location Name: Park T-4 Pad
Location ID: 428521



Apr 12, 2021 at 9:54:58 AM
+40.3344, -104.4388
Weld
Colorado Oil & Gas Conservation Commission



Apr 12, 2021 at 9:55:06 AM
+40.3344, -104.4387
Weld
Colorado Oil & Gas Conservation Commission

Photo #29 Trash

Photo #30 Stained Soil

Inspection Photos
Location Name: Park T-4 Pad
Location ID: 428521




Photo #31 Unmarked Risers



Photo #32 Unused Equipment

Inspection Photos
Location Name: Park T-4 Pad
Location ID: 428521



Photo #33 Unused Equipment

Photo #34 Unmarked Riser

Inspection Photos
Location Name: Park T-4 Pad
Location ID: 428521



Photo #35 Trash



Photo #36 Unused Equipment

Inspection Photos
Location Name: Park T-4 Pad
Location ID: 428521



Photo #37 Stained Soil & Equipment

Photo #38 Stained Soil

Inspection Photos
Location Name: Park T-4 Pad
Location ID: 428521



Apr 12, 2021 at 10:03:01 AM
+40.3345, -104.4380
Weld
Colorado Oil & Gas Conservation Commission



Apr 12, 2021 at 10:03:35 AM
+40.3345, -104.4378
Weld
Colorado Oil & Gas Conservation Commission

Photo #39 Unused Equipment

Photo #40 Jersey Barriers

Inspection Photos
Location Name: Park T-4 Pad
Location ID: 428521





Photo #41 Unused Equipment

Photo #42 Unmarked Riser & Trash

Inspection Photos
Location Name: Park T-4 Pad
Location ID: 428521



Apr 12, 2021 at 10:10:42 AM
+40.3344,-104.4385
Weld
Colorado Oil & Gas Conservation Commission

Photo #43 Trash



Apr 12, 2021 at 10:10:52 AM
+40.3344,-104.4385
Weld
Colorado Oil & Gas Conservation Commission

Photo #44 Stained Soil

Inspection Photos
Location Name: Park T-4 Pad
Location ID: 428521




Photo #45 Stained Soil

Photo #46 Stained Soil and Mechanical Conditions on valve