

Inspection Photos

Location Name: North Platte P-T-34 HZ Compressor Location

Location ID: 429920



Photo #1 Location

Inspection Photos

Location Name: North Platte P-T-34 HZ Compressor Location

Location ID: 429920



Apr 12, 2021 at 1:24:19 PM
+40.3636, -104.4138
Weld
Colorado Oil & Gas Conservation Commission



Apr 12, 2021 at 1:24:24 PM
+40.3637, -104.4139
Weld
Colorado Oil & Gas Conservation Commission

Photo #2 Oily Skid & Stained soil

Photo #3 Mechanical Conditions & Oily Skid

Inspection Photos

Location Name: North Platte P-T-34 HZ Compressor Location

Location ID: 429920



Photo #4 Oily Skid



Photo #5 Oily waste in Bucket