



40.1288, -108.21461, 6004.0ft, 358°
04/12/2021 02:18:07 PM



40.12902, -108.21444, 6002.4ft, 11°
04/12/2021 02:18:40 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Wells, meter building, tanks.

API: 05-103-10231, 10041
Ant Hill Unit 19-21, 19-22 Inspection: 701500294



40.12904, -108.2144, 6009.7ft, 344°
04/12/2021 02:20:15 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Well.

API: 05-103-10231, 10041
Ant Hill Unit 19-21, 19-22 Inspection: 701500294



40.12926, -108.21437, 6015.3ft, 332°
04/12/2021 02:11:44 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Meter buildings.

API: 05-103-10231, 10041
Ant Hill Unit 19-21, 19-22 Inspection: 701500294



Photo 6. Separator.



40.12905, -108.21431, 6014.4ft, 26°
04/12/2021 02:20:59 PM



40.12898, -108.21464, 6028.1ft, 337°
04/12/2021 02:14:39 PM



40 12914, -108 21408, 6022.8ft, 343°
04/12/2021 02:21:26 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 9. Tanks.

API: 05-103-10231, 10041
Ant Hill Unit 19-21, 19-22 Inspection: 701500294



40.12903, -108.21465, 6010.6ft, 321°
04/12/2021 02:16:01 PM



40.12924, -108.21417, 6017.2ft, 82°
04/12/2021 02:23:14 PM





40.12891, -108.21462, 6011.7ft, 275°
04/12/2021 02:16:19 PM



40.12905, -108.21482, 6012.6ft, 68°
04/12/2021 02:14:11 PM



40.12929, -108.21492, 6003.2ft, 88°
04/12/2021 02:12:58 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 15. Storm water channel running off location.

API: 05-103-10231, 10041
Ant Hill Unit 19-21, 19-22 Inspection: 701500294



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 16. Storm water channel running off location.

API: 05-103-10231, 10041
Ant Hill Unit 19-21, 19-22 Inspection: 701500294