



40.1366, -108.22445, 6061.0ft, 15°
04/12/2021 03:05:30 PM




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Well.

Ant Hill Unit 13-43

API: 05-103-11268

Inspection: 701500300



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Meter building & separator.


Ant Hill Unit 13-43

API: 05-103-11268

Inspection: 701500300







40.137, -108.22401, 6059.5ft, 231°
04/12/2021 03:08:40 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Chemical label.

Ant Hill Unit 13-43

API: 05-103-11268

Inspection: 701500300



40.13651, -108.22435, 6056.7ft, 329°
04/12/2021 03:04:55 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 7. Ruts on location.

Ant Hill Unit 13-43

API: 05-103-11268

Inspection: 701500300



40.13676, -108.22458, 6063.0ft, 66°
04/12/2021 03:06:09 PM