



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Ant Hill Unit 18-42

API: 05-103-10212

Inspection: 701500304



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Pump jack.

Ant Hill Unit 18-42

API: 05-103-10212

Inspection: 701500304





40.13712, -108.21042, 6070.4ft, 2° Ant
SESW S
04/12/2021 03:35:15 PM



40.13735, -108.21011, 6069.4ft, 10°
04/12/2021 03:33:18 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Meter building.

Ant Hill Unit 18-42

API: 05-103-10212

Inspection: 701500304



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Separator.

Ant Hill Unit 18-42

API: 05-103-10212

Inspection: 701500304



40.13733, -108.21042, 6075.9ft, 61°
04/12/2021 03:36:25 PM





40.13717, -108.21016, 6082.1ft, 225°
04/12/2021 03:37:52 PM



40.13705, -108.21048, 6070.3ft, 72°
04/12/2021 03:34:38 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 10. Ruts on location.

Ant Hill Unit 18-42

API: 05-103-10212

Inspection: 701500304