

Inspection Photos

Loc#334688

Operator: Caerus

Insp#:692403284

Insp Date: 4/7/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry.

April 7, 2021



Photo#2:
View of cut slope.



Photo#3:
View of fill slope.

April 7, 2021