

Inspection Photos

API: 071-07387

Operator: WAPITI OPERATING LLC

Inspection Date: 4/12/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07387 | Date: 4/12/2021

Inspection Photos



Photo 1. There is vehicle rutting along the access road. Areas of rutting need to be stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07387 | Date: 4/12/2021

Inspection Photos



Photo 2. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07387 | Date: 4/12/2021

Inspection Photos



Photo 3. There is produced water leaking from the wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07387 | Date: 4/12/2021