

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Colorado Oil and Gas Conservation Commission
40.60347, -104.06674, 4712.5ft, 263°
04/07/2021 13:01:11



Colorado Oil and Gas Conservation Commission
40.60338, -104.06707, 4855.8ft, 177°
04/07/2021 13:05:35

Photo 1 – Pumping Unit

Photo 2 – Tank Battery Sign

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Photo 3 – Tank Battery

Photo 4 – Heater Treater

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Photo 5 – Gas Engine Exhaust

Photo 6 – Stained Soil at Gas Engine

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Photo 7 – Stained Soil at Gas Engine

Photo 8 – Bucket at Gas Engine – Oily Waste, no cover

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Photo 9 – Stained Soil at Gas Engine

Photo 10 – Stained Soil at Gas Engine

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Photo 11 – Stained Soil at Gas Engine

Photo 12 – Stained Soil at Gearbox

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Colorado Oil and Gas Conservation Commission
40.6038, -104.0667, 4877.5ft, 66°
04/07/2021 13:02:46



Colorado Oil and Gas Conservation Commission
40.60348, -104.0666, 4868.4ft, 179°
04/07/2021 13:03:21

Photo 13 – Mechanical Conditions at Gearbox

Photo 14 – Concrete Vault Still missing Signage

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Photo 15 – Flare

Photo 16 – Stained Soil at Flare