

Inspection Photos
Operator: Logos Operating
Facility: 067-07949
Date: 4/12/2021



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing with sand dropseed.



Photos 3/4. View of dense kochia debris around tank (left), and within the northeastern project area (right)



Photo 5. View of the reference area comprised of irrigated grass field with grasses not identifiable at this time.