

Inspection Photos

4/12/2021

Operator: CAERUS PICEANCE LLC # 10456

Location ID: 335812

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335812



Photo 1: 2011 Google Earth Aerial imagery. Photo shows pits on the Location prior closure and interim reclamation



Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335812



Photo 2: 2014 Google Earth aerial image. Photo shows pits have been closed and interim reclamation conducted.




Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335812



Photo 3: Aerial imager of the Location taken 4/12/2021. Photo shows interim areas on the east end of the Location (top of photo) have been disturbed. Areas require reclamation.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335812



20210412

Photo 4: See comments under photo 3.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335812



Photo 5: Photo taken from the eastern interim areas of the Location, facing north. Photo shows interim areas re-disturbed by Operator.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335812



Photo 6: Photo taken from the eastern interim areas of the Location, facing west. Photo shows interim areas re-disturbed by Operator. Areas require reclamation. Various trash debris was also observed within these disturbed areas.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335812



Photo 7: Photo taken from the eastern interim areas of the Location, facing west. Photo shows interim areas re-disturbed by Operator. Areas require reclamation.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335812



Photo 8: Photo taken from the eastern interim areas of the Location, facing south. Photo shows interim areas re-disturbed by Operator. Areas require reclamation.



Inspection Photos

Operator Name: CAERUS PICEANCE LLC # 10456

Location ID: 335812



Photo 9: Photo taken from the eastern interim areas of the Location, facing east. Photo shows interim areas re-disturbed by Operator. Areas require reclamation.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335812



Photo 10: Photo taken from the interim areas on the north end of the Location, facing north. Interim reclamation progressing towards 1003 standards.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335812



Photo 11: Photo taken from the north end of the Location. Photo shows soil stockpiled on the Location; unclear if this is the topsoil from the disturbed areas.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335812



Photo 12: Photo shows unused signs associated with PAd wells stored on the Locaiton.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335812



Photo 13: Photo shows the wildlife netting at the methanol tank is inadequate to prevent wildlife access to the containment BMP.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335812



Photo 14: Photo shows the wildlife netting at the methanol tank is inadequate to prevent wildlife access to the containment BMP

