

Inspection Photos
Operator: Logos Operating
Facility: 067-05592
Date: 4/12/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing with smooth brome and sand dropseed.



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of the reference area comprised of crop field, largely fallow at this time, with grasses such as crested wheatgrass and smooth brome.