

Inspection Photos
Location Name: Gregory 0780 S9 Pad
Location ID: 439603



Photo 1. Overview of Gregory side of location taken at entrance facing northeast.



Photo 2. Overview of Janet side of location taken at entrance facing southeast.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Gregory 0780 S9 Pad
Location ID: 439603



Photo 3. Overview of signs at entrance. No new operator information or contact information on signs.



Photo 4. Incomplete wellhead sign.



Inspection Photos
Location Name: Gregory 0780 S9 Pad
Location ID: 439603



Photo 5. Incomplete wellhead sign.



Photo 6. Incomplete wellhead signs.



Inspection Photos
Location Name: Gregory 0780 S9 Pad
Location ID: 439603



Photo 7. Incomplete wellhead signs.



Photo 8. Incomplete wellhead signs.



Inspection Photos
Location Name: Gregory 0780 S9 Pad
Location ID: 439603



Photo 9. Incomplete wellhead sign.



Photo 10. Incomplete wellhead sign.



Inspection Photos
Location Name: Gregory 0780 S9 Pad
Location ID: 439603



Photo 11. Incomplete wellhead signs.



Photo 12. Inaccurate tank label.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources