

Inspection Photos
Location Name: Mutual 0780 S17 Pad
Location ID: 324757



Photo 1. Overview of location taken at entrance facing northeast.



Photo 2. Incomplete wellhead sign.

Inspection Photos
Location Name: Mutual 0780 S17 Pad
Location ID: 324757



Photo 3. Incomplete wellhead sign.



Photo 4. Incomplete wellhead sign.



Inspection Photos
Location Name: Mutual 0780 S17 Pad
Location ID: 324757



Photo 5. Incomplete wellhead sign.



Photo 6. Incomplete wellhead sign.



Inspection Photos
Location Name: Mutual 0780 S17 Pad
Location ID: 324757



Photo 7. Incomplete wellhead sign.



Photo 8. Incomplete wellhead sign.



Inspection Photos
Location Name: Mutual 0780 S17 Pad
Location ID: 324757



Photo 9. Incomplete wellhead sign.



Photo 10. Inaccurate tank label.

